



PeopleCounter Xtreme

Installation Instructions

THE PEOPLECOUNTER XTREME IS A TOTALLY SEALED ELECTONIC COUNTER WHICH PROJECTS AN INVISIBLE BEAM UP TO 40 FEET ACROSS THE AREA YOU WISH TO BE COUNTED.

CONTROLS AND FUNCTIONS

- (1) *SENSOR LENS.*
- (2) *POWER INDICATOR – MAINTAINS GREEN LIGHT WHEN POWER IS ON.*
- (3) *ALIGNMENT INDICATOR – MAINTAINS SOLID RED LIGHT WHEN SENSOR IS ALIGNED WITH REFLECTOR.*
- (4) *BRACKET TO WALL MOUNTING HOLES.*
- (5) *RIGHT AND LEFT SENSOR ALIGNMENT SECURING SCREWS.*
- (6) *SUPERFLEX REFLECTOR – REFLECTS INFRARED BEAM BACK TO SENSOR.*
- (7) *SUPERFLEX REFLECTOR WALL MOUNTING SCREW HOLES.*
- (8) *LCD COUNTER – COUNTS TO 9,999,999 (RESET AT ANYTIME).*
- (9) *RESET/LOCK BUTTON.*



PeopleCounter Xtreme

Installation Instructions

1. FOR INSTALLATION, COUNTERS SHOULD BE PLACED WITH NO BEAMPATH OBSTRUCTIONS, APPROXIMATELY 35 INCHES HIGH FOR COUNTNG BOTH ADULTS AND CHILDREN, AND 55 INCHES HIGH FOR COUNTING ADULTS ONLY.
2. MOUNT SUPERFLEX REFECTOR (6) ONTO WALL USING A SCREW THROUGH THE MOUNTING HOLE (7).
3. MOUNT SENSOR ONTO WALL USING SCREWS THROUGH BRACKET MOUNTING HOLES (4).
4. PLUG SENSOR POWER CORD INTO ELECTRICAL OUTLET.
5. POWER INDICATOR LIGHT (2) WILL IMMEDIATELY BURN GREEN.
6. ADJUST SENSOR IN BRACKET UNTIL ALIGNMENT WITH SUPERFLEX RELECTOR IS SUCCESSFUL AND THE ALIGNMENT INDICATOR LIGHT (3) BURNS SOLID RED. A FLICKERING RED LIGHT INDICATES ALIGNMENT, BUT NOT PRECISE ALIGNMENT.
7. TIGHTEN LEFT AND RIGHT ALIGNMENT SECURING SCREWS (5) WITH PHILIPS SCREWDRIVER.
8. ATTACH DIGITAL READOUT (8) TO WALL USING ADHESIVE VELCO STRIPS.
9. TO RESET COUNTER, PUSH THE RESET BUTTON (9).
10. TO LOCK THE COUNTER RESET BUTTON, SLIDE THE RESET/LOCK BUTTON (9) ALL THE WAY DOWN INTO THE LOCKED POSITION.

The Peoplecounter X-Treme is guaranteed against manufacturing defects for a period of 1 year.

The power cord may be extended to any length; however, we accept no responsibility if polarity reversal results in damaged sensor. Please be careful. Physical damage and tampering not covered by guarantee.